



NEW MEXICO DEPARTMENT OF REVENUE
1117 N. 1ST ST. N. 1ST FLOOR ALBUQUERQUE, NM 87102

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1800 RIO GRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://enrdd.state.nm.us/ocd/District%203/district3.htm>

OIL CONS. DIV DIST. 3

JUN 19 2013

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-23-13 Operator NOBLE ENERGY API #30-0 39-21618

Property Name Northwest Well No. 1-A Location: Unit 0 Section 7 Township 26 Range 4

Well Status(Shut-In or Producing) Initial PSI: Tubing 115 Intermediate Casing 125 Bradenhead Ø

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead				
	BH	Int	Csg	Int	Csg
TIME					
5 min	Ø		125		
10 min	Ø		125		
15 min	Ø		125		
20 min	Ø		125		
25 min	Ø		125		
30 min	Ø		125		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	Ø
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD Ø

INTERMEDIATE

REMARKS:

LSE #09-000119

By Garrett Chavez

Witness

pumper
(Position)

E-mail address