



NEW MEXICO DEPARTMENT OF REVENUE
OIL CONSERVATION DIVISION, REGULATORY
5000 RIO BRAZOS ROAD, ALBUQUERQUE, NEW MEXICO 87110

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6174 FAX: (505) 334-6170
[http://emrdd.state.nm.us/ocd/District III District.htm](http://emrdd.state.nm.us/ocd/District%20III%20District.htm)

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

JUN 19 2013

Date of Test 5-6-13 Operator Noble Energy API #30-0 39-23505

Property Name Sidonillo Well No. 3-E Location: Unit F Section 8 Township 26 Range 3

Well Status (Shut-In or Producing) Initial PSI: Tubing 85 Intermediate Casing 85 Bradenhead Ø

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	Ø		85		
10 min	Ø		85		
15 min	Ø		85		
20 min	Ø		85		
25 min	Ø		85		
30 min	Ø		85		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	Ø
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD Ø

INTERMEDIATE

REMARKS:

By Farrell Chavez

Witness

pumper n-2
(Position)

E-mail address