



NEW MEXICO DEPARTMENT OF ENERGY, 1000 RIO REAZOS ROAD
ALBUQUERQUE, NEW MEXICO 87102-1000

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO REAZOS ROAD
AZTEC NM 87410
(505) 334-6179 FAX: (505) 334-6170
<http://emrdd.state.nm.us/ocd/District/003/district.htm>

OIL CONS. DIV DIST. 3

JUN 19 2013

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-30-13 Operator Noble Energy API #30-0 39-27663

Property Name Horti Well No. 2-C Location: Unit 0 Section 3 Township 26 Range 4

Well Status(Shut-In or Producing) Initial PSI: Tubing 80 Intermediate Casing 85 Bradenhead 8

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	<u>8</u>		<u>85</u>		
10 min	<u>8</u>		<u>85</u>		
15 min	<u>8</u>		<u>85</u>		
20 min	<u>8</u>		<u>85</u>		
25 min	<u>8</u>		<u>85</u>		
30 min	<u>8</u>		<u>85</u>		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing <u>8</u>	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 8

INTERMEDIATE

REMARKS:

By Favell Clum

Witness

pumpet n-2
(Position)

E-mail address