District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Revised October 10, 2003

abmit 2 Copies to appropriate

Form C-141

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

| | | | | _ | | OPERA' | | | l Report | eport |
|---|--------------|------|------|----------|-----|---|------------|------|--------------|-------|
| Name of Company Coceat Western Deilling Co. Contact Cullan Keller | | | | | | | | | | |
| Address 115 W Aztec Blued. Aztec NM & 7410 Telephone No. 320-5504 | | | | | | | | | | |
| Facility Name J.E. Droke "3" Facility Type Tank Battery | | | | | | | | | | |
| | | | | | | | | | 0.NMSF078118 | |
| 30-045-11399 LOCATION OF RELEASE | | | | | | | | | | |
| Unit Letter Section Township Range Feet from the North/South Line Feet from the East/West Line County | | | | | | | | | | |
| | } | • | | | | | | | _ * | |
| M | 17 | 32-N | 11-W | 760 | 50- | th ——— | 660 | west | San Juan | |
| LatitudeLongitude | | | | | | | | | | |
| NATURE OF RELEASE | | | | | | | | | | |
| Type of Release Water - Oil Volume of Release 5 Bb Volume Recovered 5 ga | | | | | | | | | | |
| Source of Release Tank lock | | | | | | Date and Hour of Occurrence Date and Hour of Discovery 3-6-13 | | | | |
| Was Immedia | ite Notice (| | | | | If YES, To Whom? OCD - Johnston 11:30 AM | | | | |
| ▼ Yes □ No □ Not Required | | | | | | Date and Hour 5-6-13. 2:50 pm | | | | |
| By Whom? Clan Keller | | | | | | Date and Hour 5-6-13. 2:50 2m | | | | |
| Was a Watercourse Reached? | | | | | | If YES, Volume Impacting the Watercourse. | | | | |
| Yes 🔀 No | | | | | | | | | | |
| If a Watercourse was Impacted, Describe Fully.* RCVD MAY 8 '13 | | | | | | | | | | |
| OIL CONS. DIV. | | | | | | | | | | |
| | | | | | | | | | | |
| DIST. 3 | | | | | | | | | | |
| Describe Cause of Problem and Remedial Action Taken.* | | | | | | | | | | |
| Leak around linch collar on back of tank. | | | | | | | | | | |
| Leak around linch collar on back of tank. Called WW water truck and Tripples. We set a bank for the oil. | | | | | | | | | | |
| Drained lenking tank | | | | | | | | | | |
| Describe Area Affected and Cleanup Action Taken.* | | | | | | | | | | |
| In side fire well on back side of tent | | | | | | | | | | |
| TV DIGE the met. or dack since is | | | | | | | | | | |
| | | | | | | | | | | |
| I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and | | | | | | | | | | |
| regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger | | | | | | | | | | |
| public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability | | | | | | | | | | |
| should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health | | | | | | | | | | |
| or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other | | | | | | | | | | |
| federal, state, or local laws and/or regulations. | | | | | | | | | | |
| Signature: Oh Ku | | | | | | Approved by District Supervisor: OIL CONSERVATION DIVISION Approved by District Supervisor: | | | | |
| | | | | | | | | | | |
| Title: Louse Operator | | | | | | | | | | |
| Λ | | | | | | | `Approval: | | Attached | |
| Date: 5-6-13 Phone: 505-320-954 | | | | | | | | | | |

* Attach Additional Sheets If Necessary

NJK1329747612