

Durham, John, EMNRD

From: Busse, Dollie L <Dollie.L.Busse@conocophillips.com>
Sent: Monday, November 04, 2013 1:25 PM
To: Durham, John, EMNRD
Subject: FW: Decker A 2E (3004525676) - P&A/Cathodic Equipment

Hi John,

My information below was incorrect, the Cathodic equipment left on location is servicing the Decker A 3 (3004520743). Please let me know if you have any questions or need additional information.

Thanks!
Dollie

From: Busse, Dollie L
Sent: Monday, November 04, 2013 10:59 AM
To: John.Durham@state.nm.us
Subject: Decker A 2E (3004525676) - P&A/Cathodic Equipment

Hi John,

I've found the Decker A 2F that is scheduled to be P&A'd early in 2014 and the Decker A 1B that is producing. I'm waiting for confirmation that the Cathodic equipment left on location at the Decker A 2E was left to protect these wells. They are all in Section 3, T31N, R12W. I'll let you know as soon as I hear back.

Thanks for the heads up!
Dollie

Dollie L. Busse | Staff Regulatory Technician | ConocoPhillips | San Juan Business Unit | P.O. Box 4289 | Farmington, NM 87499 | Office: 505-324-6104 | E-mail: dollie.l.busse@cop.com

Safety People Integrity Responsibility Innovation Teamwork