

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office to
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR Initial Report Final Report

Name of Company ConocoPhillips	Contact Lisa Hunter
Address 3401 East 30th St, Farmington, NM	Telephone No. (505) 326-9786
Facility Name: San Juan 31-6 #205R	Facility Type: Gas Well

Surface Owner Federal	Mineral Owner Federal	API No. 3003925691
------------------------------	------------------------------	---------------------------

LOCATION OF RELEASE


Unit Letter G	Section 4	Township 30N	Range 6W	Feet from the 2510	North/South Line North	Feet from the 1850	East/West Line East	County Rio Arriba
-------------------------	---------------------	------------------------	--------------------	------------------------------	----------------------------------	------------------------------	-------------------------------	-----------------------------

Latitude **36.8419** Longitude **-107.46498**

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 64 BBLs	Volume Recovered 60 BBLs
Source of Release Tank overflow due to faulty Transfer Pump	Date and Hour of Occurrence Unknown	Date and Hour of Discovery 10-21-13 @ 11:30 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Brandon Powell, NMOCD Shari Ketcham, BLM	
By Whom? Lisa Hunter	Date and Hour 10/21/13 @ 4:00 p.m. (Phone) & Email follow-up 10/21/13 @ 4:09 p.m. (Voice messg) & Email follow-up	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A	RCVD OCT 24 '13	
Describe Cause of Problem and Remedial Action Taken.* Transfer pump had malfunctioned and didn't restart, causing two tanks on location to overflow. 64 BBLs of Produced Water was released and contained within the Berm. Water truck was called and 60 BBLs was recovered.		
Describe Area Affected and Cleanup Action Taken.* ConocoPhillips will assess the soil to determine a path forward for clean-up if necessary.		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Lisa Hunter	Approved by Environmental Specialist: 	
Title: Field Environmental Specialist	Approval Date: 11/7/2013	Expiration Date:
E-mail Address: Lisa.Hunter@cop.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: October 22, 2013 Phone: (505) 326-9786		

* Attach Additional Sheets If Necessary

NSK1331130981