



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emrdr.state.nm.us/ocd/District III/3district.htm](http://emrdr.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3

JUL 15 2013

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7.5.13 Operator Huntington Energy API #30-039-05441

Property Name CLM Well No. 89 Location: Unit m Section 17 Township 4N Range 26W

Well Status(Shut-In or Producing) Initial PSI: Tubing 100 Intermediate Casing 150 Bradenhead 14

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	<u>2</u>		<u>125</u>		
10 min	<u>2</u>		<u>125</u>		
15 min	<u>3</u>		<u>125</u>		
20 min	<u>3</u>		<u>125</u>		
25 min	<u>3</u>		<u>130</u>		
30 min	<u>3</u>		<u>138</u>		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	<u>✓</u>
Nothing	
Gas	<u>✓</u>
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

☒ CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 2 INTERMEDIATE

REMARKS:

no fluid, you can see gas fumes coming out of bradenhead

By D. S. Muel

Witness

(Position)

E-mail address