



NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
<http://ernrd.state.nm.us/ocd/DistrictIII/3district.htm>

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

AUG 23 2013

(submit 1 copy to above address)

Date of Test 8.19.13 Operator David Aguirre API #30-0 45-28563

Property Name 37.5 #5 Well No. #5 Location: Unit A Section 18 Township 31 Range 7

Well Status(Shut-In or Producing) Initial PSI: Tubing 466 Intermediate NA Casing -4 Bradenhead 2

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

FLOW CHARACTERISTICS

Testing TIME	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
5 min	0	-	-4		
10 min	0		-6		
15 min	0		-6		
20 min					
25 min					
30 min					

BRADENHEAD INTERMEDIATE

Steady Flow.	
Surges	
Down to Nothing	<input checked="" type="checkbox"/>
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE \_\_\_\_\_

REMARKS:

Light blow for 7 min - Dead

By David Aguirre  
SWD MSD  
(Position)

Witness Mona Cuello

E-mail address \_\_\_\_\_