



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emrdr.state.nm.us/ocd/District III/3district.htm](http://emrdr.state.nm.us/ocd/District%20III/3district.htm)
OIL CONS. DIV DIST. 3

AUG 21 2013

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6-27-13 Operator David Aguirre API #30-0 45-28703

Property Name ST 32.8 #303 Well No. 303 Location: Unit Section 14 Township 31 Range 8

Well Status(Shut-In or Producing) Initial PSI: Tubing 206 Intermediate 11 Casing 466 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>	<u>11</u>	<u>469</u>	<u>0</u>	<u>474</u>
10 min	<u>0</u>	<u>11</u>	<u>470</u>	<u>0</u>	<u>473</u>
15 min	<u>0</u>	<u>11</u>	<u>471</u>	<u>0</u>	<u>474</u>
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	<u>✓ 15 sec</u>
Nothing	<u>✓</u>
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0

REMARKS:

By [Signature]
SUD. M50
(Position)

Witness [Signature]

E-mail address _____