



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District II/3district.htm](http://emnr.state.nm.us/ocd/District%20II/3district.htm)

OIL CONS. DIV DIST. 3

AUG 19 2013

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8/9/2013 Operator BmG API #30-0 39-22592

Property Name EPCmu E-19 Well No. 40 Location: Unit E Section 19 Township 27N Range 1E

Well Status(Shut-In or Producing) Initial PSI: Tubing 0 Intermediate Casing 50 Bradenhead 11

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE					FLOW CHARACTERISTICS	
	Bradenhead		INTERM			BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg		
TIME							
5 min	<u>0</u>		<u>50</u>			Steady Flow <u>NO</u>	
10 min	<u>0</u>		<u>50</u>			Surges <u>NO</u>	
15 min	<u>0</u>		<u>50</u>			Down to Nothing <u>yes</u>	
20 min						Nothing <u>yes</u>	
25 min						Gas <u>NO</u>	
30 min						Gas & Water <u>NO</u>	
						Water <u>NO</u>	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

REMARKS: Bradenhead had 11 PSI Blew down within a min.
and stayed dead for Duration of test

By Bernie Velazquez
Lease operator
(Position)

Witness

E-mail address