



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

AUG 19 2013

(submit 1 copy to above address)

Date of Test 8/8/2013 Operator Bmg API #30-0 39-23213

Property Name Epcmu P-5 Well No. 33 Location: Unit P Section 5 Township 26N Range 1E

Well Status(Shut-In or Producing) Initial PSI: Tubing 70 Intermediate Casing 18 Bradenhead 22

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>5</u>		<u>18</u>		
10 min	<u>0</u>		<u>18</u>		
15 min	<u>0</u>		<u>18</u>		
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow	<u>NO</u>	
Surges	<u>NO</u>	
Down to Nothing	<u>yes</u>	
Nothing	<u>yes</u>	
Gas	<u>NO</u>	
Gas & Water	<u>NO</u>	
Water	<u>NO</u>	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

REMARKS: Braden head had 22 PSI Blew down in 6 min
Stayed Dead for Rest of 15 min Test

By Banner Velazquez
Lease operator
(Position)

Witness

E-mail address