



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/District/HW3district.htm>

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

AUG 19 2013

Date of Test 8/8/2013 Operator BMG API #30-0 39-23226

Property Name EPCMU K-5 Well No. 34 Location: Unit K Section 5 Township 26N Range 1E

Well Status(Shut-In or Producing) Initial PSI: Tubing 85 Intermediate Casing 18 Bradenhead 5

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead		INTERM	
		Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>18</u>		
10 min	<u>0</u>		<u>18</u>		
15 min	<u>0</u>		<u>18</u>		
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow	<u>NO</u>	
Surges	<u>NO</u>	
Down to Nothing	<u>yes</u>	
Nothing	<u>yes</u>	
Gas	<u>NO</u>	
Gas & Water	<u>NO</u>	
Water	<u>NO</u>	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

REMARKS: Braden head had 5PSI Blewdown stayed dead
for Duration of Test

By Bernie Velazquez
Lease Operator
(Position)

Witness

E-mail address