



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/District/III/3district.htm>

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

AUG 15 2013

Date of Test 8/7/2013 Operator Western Minerals and Oil API #30-0 4506248

Property Name Marron Well No. 2 Location: Unit Section 27 Township 37N Range 8W

Well Status (Shut-In or Producing) Initial PSI: Tubing 6 Intermediate — Casing 23 Bradenhead 1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead		INTERM	
		Int	Csg	Int	Csg
TIME					
5 min	<u>⊖</u>				<u>23</u>
10 min	<u>⊖</u>				<u>23</u>
15 min	<u>⊖</u>				<u>23</u>
20 min	<u>⊖</u>				<u>23</u>
25 min	<u>⊖</u>				<u>23</u>
30 min	<u>⊖</u>				<u>23</u>

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing <u>X 2 seconds</u>	
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD ⊖

INTERMEDIATE —

REMARKS: Blew down to nothing in 2 seconds.
Never built back up and no liquids came out

By Bobi Chenault
Lease Operator
(Position)

Witness

E-mail address bobecc@nm.com