



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/District/III/3distrct.htm>

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

AUG 21 2013

Date of Test 8.12.13 Operator David Aguirre API #30-0 39-44518
Property Name SJ 30-4 SWD Well No. 2 Location: Unit 23 Section 23 Township 20 Range 7
Well Status (Shut-In or Producing) Initial PSI: Tubing 617 Intermediate Casing -7 Bradenhead 7

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
5 min	<u>22</u>	<u>-</u>	<u>-7</u>		
10 min	<u>1</u>	<u>-</u>	<u>-7</u>		
15 min	<u>.01</u>		<u>-7</u>		
20 min	<u>.01</u>		<u>-7</u>		
25 min	<u>.02</u>		<u>-7</u>		
30 min	<u>.03</u>		<u>-7</u>		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow <u>✓</u>	
Surges <u> </u>	
Down to Nothing <u> </u>	<u>2200</u>
Nothing <u> </u>	
Gas <u>✓</u>	
Gas & Water <u> </u>	
Water <u> </u>	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 2.2 INTERMEDIATE

REMARKS:

Small (LEL) BH need to shut Intermediate!
Gas test.

By

David Aguirre

Witness

Monica Cuello

(Position)

E-mail address