



NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

RCVD APR 29 '13

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

OIL CONS. DIV.  
DIST. 3

Date of Test 4/29/2013 Operator Burlington API #30-0 39-27617

Property Name San Juan 27-4 Unit Well No. 69M Location: Unit L Section 34 Township 27 Range 4

Well Status (Shut-In or Producing) Initial PSI: Tubing 209 Intermediate 4.6 Casing 225 Bradenhead 0.1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

| Testing | PRESSURE |            |     |        |     |
|---------|----------|------------|-----|--------|-----|
|         | BH       | Bradenhead |     | INTERM |     |
|         |          | Int        | Csg | Int    | Csg |
| TIME    |          |            |     |        |     |
| 5 min   | 0        | 4.5        | 228 | 3.0    | 232 |
| 10 min  | 0        | 4.5        | 229 | 1.0    | 232 |
| 15 min  | 0        | 4.5        | 230 | 0      | 233 |
| 20 min  |          |            |     |        |     |
| 25 min  |          |            |     |        |     |
| 30 min  |          |            |     |        |     |

| FLOW CHARACTERISTICS |              |
|----------------------|--------------|
| BRADENHEAD           | INTERMEDIATE |
| Steady Flow          |              |
| Surges               |              |
| Down to Nothing      | X            |
| Nothing              |              |
| Gas                  |              |
| Gas & Water          |              |
| Water                |              |

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

BH pressure blew down to nothing in 1 sec, slight leak on one of the fittings on intermediate gauge. Intermediate is through 1", was obstructed w/ dirt in outer valve, blew down in 12 min 25 sec w/ valve obstruction partially cleared

By

A. H.  
MSD

(Position)

Witness

Jonathan D. Kelly

E-mail address \_\_\_\_\_