



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

RCVD APR 29 '13

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

OIL CONS. DIV.
DIST. 3

Date of Test 4/29/2013 Operator Burlington API #30-0 39-30618

Property Name San Juan 27 4 Unit Well No. 109A Location: Unit B Section 23 Township 27 Range 4

Well Status (Shut-In or Producing) Initial PSI: Tubing 185 Intermediate 26.2 Casing 189 Bradenhead -1.6

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	26.2	189	0.2	190
10 min	0	26.1	189	0.0	190
15 min	0	26.1	189	0.0	191
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	X	X
Nothing		
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 0.0

REMARKS:

BH had suction for 10 sec, Intermediate had moderate blow for 3 min, then light blow to a whisper in 6 min, down to nothing in 11 min. 5 min shut in showed on gauge but blew a little when valve checked TSTM

By [Signature]
MISO
(Position)

Witness [Signature]
Jonell D. Kelly

E-mail address _____