

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

JK 1/14/2014
☒ Initial Report

☒ Final Report

Name of Company: BP America Production Company	Contact: Courtney Cochran	
Address: 200 Energy Ct. Farmington, NM 87401	Telephone No.: 505-326-9457	
Facility Name: Florance 027S CDP	Facility Type: Natural Gas Well and Delivery Point	
Surface Owner: Federal	Mineral Owner: Federal	API No.: 3004533130

LOCATION OF RELEASE

Unit Letter L	Section 26	Township 29N	Range 09W	Feet from the 1670	North/South Line South	Feet from the 990	East/West Line West	County: San Juan
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	----------------------	------------------------	------------------

Latitude 36.69412 Longitude 107.75545

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 56 bbl	Volume Recovered: none
Source of Release	Date and Hour of Occurrence: 9/15/2013	Date and Hour of Discovery: 9/16/2013
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Brandon Powell - NMOCD	
By Whom? Courtney Cochran - BP	Date and Hour: noon - 9/16/2013	RCVD SEP 20 '13
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. OIL CONS. DIV. DIST. 3	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

Due to flooding rains rainwater filled and overflowed three BGT's on location. The location is shut-in and the BGT's will be pulled down.

Describe Area Affected and Cleanup Action Taken.*

Produced water diluted with rainwater and moved along with floods. BGT's will be pulled down with remaining fluid being disposed of.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Courtney Cochran		Approved by Environmental Specialist: 	
Title: Field Environmental Advisor		Approval Date: 1/14/2014	Expiration Date:
E-mail Address: Courtney.Cochran@bp.com		Conditions of Approval:	
Date: 9/18/2013 Phone: 505-326-9457		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

WJK 1401431049