



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 3-11-14 Operator Burlington Res API # 30-0 39-24518

Property Name San Juan 30-6 W SWD Well # 2 Location: Unit 23 Twn 30 Rge 7

Land Type:

State
Federal ✓
Private
Indian

Well Type:

Water Injection
Salt Water Disposal ✓
Gas Injection
Producing Oil/Gas
Pressure observation

Temporarily Abandoned Well (Y/N) N TA Expires:

Casing Pres. 0
Bradenhead Pres. 4.3
Tubing Pres. 1124
Int. Casing Pres. N/A

Tbg. SI Pres.
Tbg. Inj. Pres.

Max. Inj. Pres. DIST. 3
OIL CONS. DIV.

REC'D MAR 11 '14

Pressured annulus up to psi. for mins. Test passed/failed failed

REMARKS:

Packer Set at 3036

top of 3072

Well started injecting before water hauler arrived
after deep of being down. then went down before 4th test

By David Aguirre
(Operator Representative)

Witness Mona Kunkling
(NMOCD)

SWD MSO
(Position)

Revised 02-11-02