



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 3-17-14 Operator Wuon Energy API #30-0 33-24620
Property Name 19BU Well No. 493 Location: Unit Section 25 Township 31 Range 7
Well Status(Shut-In or Producing) Initial PSI: Tubing 3 Intermediate N/A Casing 19 Bradenhead 1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead		INTERM	
		Int	Csg	Int	Csg
TIME					
5 min	0		16		
10 min	0		14		
15 min	0		12		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	DISC. 3
Down to Nothing	
Nothing	OIL CONS. DIV.
Gas	
Gas & Water	RCVD MAR 17'14
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

Well dead at 10 seconds

Well shut down when started test

By Johna

Witness Monica Trevino

(Position)

E-mail address