



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 3-17-14 Operator Wuon Energy API #30-0 39-29933
Property Name IEBU Well No. 493A Location: Unit 25 Township 31 Range 7
Well Status (Shut-In or Producing) Initial PSI: Tubing 32 Intermediate 1/A Casing 29 Bradenhead 0.3

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	0		31		
10 min	0		34		
15 min	0		34		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	
Gas	DIST. 3
Gas & Water	
Water	OIL CONS. DIV.

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

RCVD MAR 17 '14

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 1/A

REMARKS:

BH cleared at 3 seconds

Will possibly need to clear out BH

By Johna Lewis

Witness Monica Kuehling

(Position)

E-mail address _____