



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 3-21-14 Operator Energex API #30-0 45-29139
Property Name Flora Vista Well No. 2 Location: Unit N Section 19 Township 30 Range 11
Well Status (Shut-In or Producing) Initial PSI: Tubing 4 Intermediate V/A Casing 4 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE					
	BH	Bradenhead	INTERM	Int	Csg	
5 min	<u>0</u>					
10 min	<u>0</u>					
15 min	<u>0</u>					
20 min						
25 min						
30 min						

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	<u>DIST. 3</u>
Nothing <u>4</u>	
Gas	<u>OIL CONS. DIV.</u>
Gas & Water	<u>RCVD MAR 21 '14</u>
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE V/A

REMARKS:

Nothing when opened.

By Francis Candlish

Witness Monica Tuckling

(Position)

E-mail address _____