



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 3-12-2014 Operator COPC API # 30-0 39-24518

Property Name San Juan 30-6 Unit Well # 2 Location: Unit D Sec 23 Twn 30 Rge 7

Land Type:

State _____
Federal ☒ _____
Private _____
Indian _____

Well Type:

Water Injection _____
Salt Water Disposal ☒ _____
Gas Injection _____
Producing Oil/Gas _____
Pressure observation _____

Temporarily Abandoned Well (Y/N): No TA Expires: _____

Casing Pres. 0 Tbg. SI Pres. _____ Max. Inj. Pres. _____
Bradenhead Pres. 0 Tbg. Inj. Pres. _____
Tubing Pres. 668
Int. Casing Pres. _____

Pressured annulus up to 560 psi. for 30 mins. Test passed/~~failed~~

REMARKS: Gained about 10 PSI, but was steady last 10 min.

By David Aguirre Witness Paul Wicks
(Operator Representative) (NMOCD)

SWD mso
(Position)

Revised 02-11-02