

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

RECEIVED

FORM APPROVED
OMB NO. 1004-0137
Expires July 31, 2010

SUNDRY NOTICES AND REPORTS ON WELLS

MAR 21 2014

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

5. Lease Serial No.
Jicarilla Contract 117
6. If Indian, Allottee or Tribe Name
Jicarilla Apache

SUBMIT IN TRIPLICATE - Other instructions on page 2

7. If Unit or CA/Agreement, Name and/or No.

1. Type of Well

Oil Well Gas Well Other

8. Well Name and No.

Jicarilla 117E 3

2. Name of Operator

ENERGEN RESOURCES CORPORATION

9. API Well No.

30-039-06200

3a. Address

2198 Bloomfield Highway; Farmington, NM 87401

3b. Phone No. (include area code)

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1090' FSL, 1650' FWL, Sec. 34, T26N, R3W, N.M.P.M.

10. Field and Pool, or Exploratory Area

Tapacito Pictured Cliffs
Blanco Mesaverde

11. County or Parish, State

Rio Arriba NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

- Notice of Intent
 Subsequent Report
 Final Abandonment Notice

- Acidize Deepen Production (Start/Resume) Water Shut-Off
 Alter Casing Fracture Treat Reclamation Well Integrity
 Casing Repair New Construction Recomplete Other _____
 Change Plans Plug and Abandon Temporarily Abandon
 Convert to Injection Plug Back Water Disposal

BP

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)

The Jicarilla 117 E3 failed a bradenhead test on 3/19/2014. Energen Resources intends to investigate the cause of the failure and determine whether to make repairs and return to production or permanently plug and abandon the well.

RCVD MAR 26 '14
OIL CONS. DIV.

DIST. 3

14. I hereby certify that the foregoing is true and correct

Name (Printed/Typed)

Collin Placke

Title District Engineer

Signature

Collin Placke

Date 3/21/14

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Original Signed: Stephen Mason

Title

Date MAR 24 2014

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

NR0002