



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/District/III/3distric.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-1-14 Operator Four Star API #30-0 45-06714
Property Name Charleyah Well No. 2 Location: Unit Section 12 Township 27 Range 9
Well Status (Shut-In or Producing) Initial PSI: Tubing 58 Intermediate VA Casing 48 Bradenhead 38

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE				
	Bradenhead		INTERM		
	BH	Int	Csg	Int	Csg
5 min	0		55		
10 min	0		55		
15 min	0		55		
20 min	0		55		
25 min	0		55		
30 min	0		55		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow <u>chip water</u>	
Surges <u> </u>	<u>DIST. 2</u>
Down to Nothing <u> </u>	
Nothing <u> </u>	<u>OIL CONS. DIV.</u>
Gas <u> </u>	
Gas & Water <u> </u>	<u>RCVD APR 1 '14</u>
Water <u> </u>	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 2

INTERMEDIATE VA

REMARKS:

down to 0 in 3 seconds - flowed 1/2 gallon clear
water in 25 seconds to heavy chip lighter chip at 5 min
at 5-10-15-20-25-30

By Randy G. Galt
calder source
(Position)

Witness Monica L. L. L.
Water Sampling

E-mail address Randy.Galt@state.nm.us

1 gallon clear water in 30 min