

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 87240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

*Federal well*

Form C-103  
May 27, 2004

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. <b>30-045-29863</b>
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other		5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator <b>XTO Energy Inc.</b>		6. State Oil & Gas Lease No. <b>142060462</b>
3. Address of Operator <b>2700 Farmington Ave., Bldg. K, Ste 1 Farmington, NM 87401</b>		7. Lease Name or Unit Agreement Name: <b>UTE INDIANS A</b>
4. Well Location Unit Letter <b>I</b> : <b>2600</b> feet from the <b>SOUTH</b> line and <b>1000</b> feet from the <b>EAST</b> line Section <b>02</b> Township <b>31N</b> Range <b>14W</b> NMPM County <b>SAN JUAN</b>		8. Well Number <b>27</b>
11. Elevation (Show whether DR, RKB, RT, GR, etc.) <b>6100'</b>		9. OGRID Number <b>167067</b>
Pit or Below-grade Tank Application <input type="checkbox"/> or Closure <input type="checkbox"/> Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____ Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____		10. Pool name or Wildcat <b>UTE DOME MORRISON</b>

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐

OTHER: **CORRECTION OF ORIGINAL PAPERWORK** ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

The APD was originally approved as Ute Dome DK completion. A hearing by the NMOC in Santa Fe (December, 1998) granted permission to complete in the Morrison. The well spudded 8/1/99 & completed 11/5/99 in the Ute Dome Morrison (perfs 2580'-92'). However, the compl rpt & C104 was submitted & approved by BLM & OCD as Ute Dome DK. All prod from 11/99 to current has been rptd as Ute Dome DK. Another hearing in Aug. 2004 in Santa Fe gave approval to RC the Ute Dome DK. This was completed 1/1/2005. It was at this time we discovered that all paperwork filed in 1999 had been filed as Ute Dome DK instead of Morrison. We have attempted to correct paperwork for original completion in 1999 to Ute Dome Morrison so we can move rptd produc from Nov. 1999-Dec. 2004 to correct pool. All production from 1/5/2005 is Ute Dome DK gas.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been constructed or closed according to NMOC guidelines ☐ , a general permit ☐ or an (attached) alternative OCD-approved plan ☐

SIGNATURE *Holly C. Perkins* TITLE REGULATORY COMPLIANCE TECH DATE 8/2/05  
Type or print name **HOLLY C. PERKINS** E-mail address: Regulatory@xtoenergy.com Telephone No. **505-324-1090**

For State Use Only

APPROVED BY *For file only* TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
Conditions of Approval, if any: