



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emrnr.state.nm.us/ocd/District III/3district.htm](http://emrnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

OIL CONS. DIV DIST. 3

APR 11 2014

Date of Test 4-2-14 Operator Fairstar Oil gas API #30-045-27734

Property Name Federal Well No. 64 Location: Unit 6 Section 10 Township 31 Range 7

Well Status (Shut-In or Producing) Initial PSI: Tubing 1 Intermediate X Casing 63 Bradenhead 1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	1	63		
10 min	0	1	63		
15 min	0	1	63	X	
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing <u>X 7sec</u>	X
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE X

REMARKS:

Blew dead in 7sec

By Randy Calcat

Witness

Moussa Kuchling

Caldor Service
(Position)

E-mail address Randy.C@CaldorService.com