

## MEW MIEXICO IEMERGY, MIMERAILS & MATURAIL RIESOURCES IDEPARTMIENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170 http://emnrd.state.nm.us/ocd/District Ill/3distric.htm

DIST. 3

## **BRADENHEAD TEST REPORT**

OIL CONS. DIV. RCVD APR 2411 A

		(submit 1 copy to above	address)	RCVD APR 24 14
Date of Test 4	34-14	Operator Elmitida	H API#	30-0 39-23312
Date of Test 4-24-14 Operator Elm Grage API #30-0 39-23372  Property Name Mulin White Well No. 23 Location: Unit Section 7 Township 23 Range 4				
Well Status(Shut-In or Producing) Initial PSI: Tubing // Intermediate // Casing 40 Bradenhead 40				
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH				
Testing Braden BH Int	PRESSURE  head INTE  Csg Int	RM Csg	FLOW CHA BRADENHEAD	ARACTERISTICS INTERMEDIATE
TIME 33	26		/	
10 min 22	16	Surges		
15 min /6	16	Down to Noth	ing	
20 min //	6			
25 min 5	5			
30 min /	1 . '	,		
Water				
CLEAR FRESH SALTY SULFUR BLACK				
5 MINUTE SHUT-IN PRESSURE BRADENHEAD INTERMEDIATE //				
REMARKS: (bloww 1th blue Sas to 50 seconds. Whe ste at 51 Seconds. Surgest Imin 17 seconds.				
Dugeat min 17 Deconds.				
By Arland Scar Witness Moula Cultury				
Prodution Forman Schematic - BH & Jud. Cusing Sus analysis BH & Jud. Cusing				
E mail address				