



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

OIL CONS. DIV.
RCVD APR 24 '14

Date of Test 4-24-14 Operator Elm Ridge Exp. API #30-0 43-20757
Property Name Sicavilla 430 Well No. 6 Location: Unit 36 Section 36 Township 23 Range 5
Well Status(Shut-In or Producing) Initial PSI: Tubing 122 Intermediate N/A Casing 99 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	0		105		
10 min	0		105		
15 min	0		102		
20 min	0		102		
25 min	0		100		
30 min	0		100		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	/
Nothing	
Gas	/
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

Shut to vapors in 9 seconds - flowed 5 min.

By Richard H. Moore
Production Foreman
(Position)

Witness Mona Tuckling
tested in 1 year
R.R.

E-mail address _____