



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emrdd.state.nm.us/ocd/District II/3district.htm](http://emrdd.state.nm.us/ocd/District%20II/3district.htm)

OIL CONS. DIV DIST. 3

MAY 01 2014

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5/01/2014 Operator Burlington API #30-045 -11406

Property Name Bonds Well No. 1 Location: Unit M Section 15 Township 32 Range 10

Well Status (Shut-In or Producing) Initial PSI: Tubing 135 Intermediate NA Casing 141 Bradenhead 155

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0		143		
10 min	0		143		
15 min	0		144		
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	X	
Nothing		
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 137

INTERMEDIATE NA

REMARKS:

Pressure blew down in 1 sec in puff through 1" valve, checked initial pressure w/ 2 gauges same pressure. Reopened BH @ 5 min shut-in after pressure taken, encountered spit of liquid, left open for an additional 20 min, no fluids to surface. Request gas & fluid analysis

By Trey Sullivan
(Position)

Witness Jonathan Kelly

E-mail address _____