



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3distric.htm](http://emnr.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-5-2014 Operator COPC API #30-0 45-23366

Property Name Calloway Well No. 2 Location: Unit A Section 22 Township 31 Range 11

Well Status(Shut-In or Producing) Initial PSI: Tubing 187 Intermediate — Casing 187 Bradenhead 6

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	—	187		
10 min	0	—	187		
15 min	0	—	187		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☒ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☒

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 5.5

INTERMEDIATE —

REMARKS:

Bradenhead flowed black water for a few seconds, then
turned clear, flowed 15 minutes. Requested water sample.

By [Signature]

Witness Paul W. [Signature]

MSU
(Position)

E-mail address —