



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District II/3district.htm](http://emnrd.state.nm.us/ocd/District%20II/3district.htm)

OIL CONS. DIV DIST. 3

MAY 06 2014

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5/6/2014 Operator West Largo API # 30-045-32015
Property Name Kendall 24 Well No. 1 Location: Unit P Section 24 Township 28 Range 10
Well Status (Shut-In or Producing) Initial PSI: Tubing 7 Intermediate NA Casing 28 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>	<u>5</u>	<u>28</u>		
10 min	<u>0</u>	<u>5</u>	<u>28</u>		
15 min	<u>0</u>	<u>5</u>	<u>28</u>		
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	<u>X</u>	
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE NA

REMARKS:

No pressure on BH

By Mr M

Witness Jonathan D. Kelly

(Position)

E-mail address _____