



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-30-14 Operator Maralex Wess API #30-0 45-33464

Property Name Centerpoint Well No. _____ Location: Unit _____ Section 24 Township 31 Range 11

Well Status (Shut-In or Producing) Initial PSI: Tubing 1440 Intermediate 10 Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>	<u>0</u>	<u>0</u>	<u>0</u>	<u>0</u>
10 min	<u>0</u>	<u>0</u>	<u>0</u>	<u>0</u>	<u>0</u>
15 min	<u>0</u>	<u>0</u>	<u>0</u>	<u>0</u>	<u>0</u>
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS

BRADENHEAD INTERMEDIATE

Steady Flow	
Surges	
Down to Nothing	<u>/ Vacuum</u>
Nothing	<u>/</u>
Gas	
Gas & Water	<u>NOT 2</u>
Water	<u>OIL CONS. DIV.</u>

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

RCVD APR 30 '14

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0

REMARKS:

BH - Nothing when opened
Int - Vacuum when opened - dead at 21 seconds.
Need vacuum gauge next test.

By _____

Witness

Monica Kuehling

(Position)

E-mail address _____