



NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

RCVD MAY 7 '14  
OIL CONS. DIV.  
DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7-MAY-2014 Operator COLEMAN API #30-0 4S-230B  
Property Name MIDDLE MESA Well No. 2 Location: Unit J Section 33 Township 2 Range 7  
Well Status(Shut-In or Producing) Initial PSI: Tubing 55 Intermediate N/A Casing 65 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min			73		
10 min			75		
15 min			77		
20 min				N/A	
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	X
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

OPENED THE BRADENHEAD AND NOTHING CAME OUT

By Bill Royce  
Lease Operator  
(Position)

Witness John Royce

E-mail address \_\_\_\_\_