



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emrdr.state.nm.us/ocd/District/III/3district.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5/16/2014 Operator COPC API #30-0 45-25114

Property Name Culpepper Martin Well No. 1E Location: Unit _____ Section 31 Township 32 Range 12

Well Status (~~Shut-In~~ or Producing) Initial PSI: Tubing 166 Intermediate _____ Casing 165 Bradenhead 135

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead		INTERM	
		Int	Csg	Int	Csg
TIME					
5 min	<u>3</u>	<u>—</u>	<u>166</u>		
10 min	<u>2</u>	<u>—</u>	<u>166</u>		
15 min	<u>2</u>	<u>—</u>	<u>166</u>		
20 min	<u>1.4</u>	<u>—</u>	<u>166</u>		
25 min	<u>1.5</u>	<u>—</u>	<u>166</u>		
30 min	<u>1.7</u>	<u>—</u>	<u>167</u>		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow <u>✓</u>	
Surges _____	
Down to Nothing _____	
Nothing _____	
Gas _____	
Gas & Water _____	
Water _____	

OIL CONS. DIV DIST. 3

MAY 16 2014

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 18.4 INTERMEDIATE _____

REMARKS:

Bradenhead blew down in 17 seconds, slight blow for
rest of 30 min. test. Requested gas anal.

By Tim Ferguson
MSO
(Position)

Witness Paul White

E-mail address _____