



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emmrnd.state.nm.us/ocd/District III/3district.htm](http://emmrnd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test April 15 Operator ENERVEST OPERATING API #30-0 45-32457

Property Name NORDHAUS Well No. 713S Location: Unit D Section 11 Township 31N Range 9W

Well Status (Shut-In or Producing) Initial PSI: Tubing 12 Intermediate Casing 8 Bradenhead 5

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead				
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>8</u>		
10 min	<u>0</u>		<u>8</u>		
15 min	<u>0</u>		<u>8</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing ☒	
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

REMARKS: Down to nothing in 3 seconds.

By Ethan Payne
Payne
(Position)

Witness

E-mail address

OIL CONS. DIV DIST. 3
MAY 07 2014