



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://omnrd.state.nm.us/ocd/District III/3dldistrict.htm](http://omnrd.state.nm.us/ocd/District%20III/3dldistrict.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-10-2014 Operator ENERVEST OPERATING API #30-0 45-32561

Property Name SEYMOUR Well No. 723S Location: Unit 1 Section 25 Township 31N Range 9W

Well Status (Shut-In or Producing) Initial PSI: Tubing 20 Intermediate Casing 8 Bradenhead 0.5

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
5 min	0		8		
10 min	0		8		
15 min	0		8		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	✓
Nothing	
Gas	
Gas & Water	
Water	

OIL CONS. DIV DIST. 3.

MAY 07 2014

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

REMARKS: Down to nothing in 4 seconds.

By Ethan Payne
Payne
(Position)

Witness

E-mail address