



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4/12/14 Operator Thompson Engineering API #30-0 45-28439

Property Name Hughes 27 G Well No. 41 Location: Unit 6 Section 27 Township 29N Range 8W

Well Status (Shut-In or Producing) Initial PSI: Tubing 48 Intermediate 144 Casing 108 Bradenhead 41

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>108</u>		
10 min	<u>0</u>		<u>108</u>		
15 min	<u>0</u>		<u>108</u>		
20 min	<u>0</u>		<u>108</u>		
25 min	<u>0</u>		<u>108</u>		
30 min	<u>0</u>		<u>108</u>		

FLOW CHARACTERISTICS
BRADENHEAD INTERMEDIATE

Steady Flow

Surges

Down to Nothing ✓

Nothing

Gas ✓

Gas & Water

Water

OIL CONS. DIV DIST. 3
MAY 15 2014

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

REMARKS:

opened valve and pressure blew down within seconds, dug up
valves.

By Theo Hampton

Witness

(Position)

E-mail address