



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 04/29/14 Operator Thompson Engineering API #30-0 45-28492
Property Name Harlie 25 #3 Well No. 4 Location: Unit B Section Township 29N Range 8E
Well Status (Shut-In or Producing) Initial PSI: Tubing 120 Intermediate 144 Casing 132 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>132</u>		
10 min	<u>0</u>		<u>132</u>		
15 min	<u>0</u>		<u>132</u>		
20 min	<u>0</u>		<u>132</u>		
25 min	<u>0</u>		<u>132</u>		
30 min	<u>0</u>		<u>132</u>		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	OIL CONS. DIV DIST. 3
Nothing <u>✓</u>	MAY 14
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

REMARKS:

Dug up bradenhead, opened all valves and not a
whisp even came out.

By Theo Hampton

Witness

(Position)

E-mail address