



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III3district.htm](http://emnrd.state.nm.us/ocd/District%20III3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 05/09/14 Operator Thompson Engineering API #30-0 45-28594
Property Name Loelofs 10 B Well No. 1\ Location: Unit B Section 10 Township 29N Range 8W
Well Status (Shut-In or Producing) Initial PSI: Tubing 3 Intermediate N/A Casing 14 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>14</u>		
10 min	<u>0</u>		<u>14</u>		
15 min	<u>0</u>		<u>14</u>		
20 min	<u>0</u>		<u>14</u>		
25 min	<u>0</u>		<u>14</u>		
30 min	<u>0</u>		<u>14</u>		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing <u>✓</u>	
Gas	
Gas & Water	
Water	

OIL CONS. DIV DIST. 3
MAY 15 2014

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE _____

REMARKS:

opened valve not even a whisper, dug up all valves
to make sure they were open properly.

By Theo Hampton

Witness _____

(Position)

E-mail address _____