



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-16-14 Operator Burlington API #30-0 45-10875
Property Name Lucene A Well No. 1 Location: Unit Section 9 Township 31 Range 10
Well Status (Shut-In or Producing) Initial PSI: Tubing 112 Intermediate 340 Casing 114 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE					FLOW CHARACTERISTICS	
	BH	Bradenhead Int	Csg	INTERM Int	Csg	BRADENHEAD	INTERMEDIATE
TIME							
5 min	0	340	114	0	118	light blow	Steady Flow
10 min	0	341	114	0	118	Surges	
15 min	0	341	114	0	120	Vapors	Down to Nothing
20 min				0	120	Nothing	
25 min				0	120	Gas	
30 min				0	120	Gas & Water	
						Water	

OIL CONS. DIV DIST. 3

MAY 16 2014

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

BH - long puff to dead in 2 seconds.
Int - hand blow to 1 min. Surge at 1.15 min -
Whistle 1.36 min - to vapors light blow at 2.5 min.

By M. J. [Signature]

Witness Monica [Signature]

(Position)

E-mail address