

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office to  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company <b>ConocoPhillips Company</b>	Contact <b>Lisa Hunter</b>
Address <b>3401 East 30<sup>th</sup> St, Farmington, NM</b>	Telephone No. <b>(505) 326-9786</b>
Facility Name: <b>San Juan 29-6 Unit 54</b>	Facility Type: <b>Natural Gas</b>

Surface Owner <b>State</b>	Mineral Owner <b>Fee</b>	API No. <b>3003907695</b>
----------------------------	--------------------------	---------------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
<b>K</b>	<b>04</b>	<b>29N</b>	<b>06W</b>	<b>1800</b>	<b>South</b>	<b>1550</b>	<b>West</b>	<b>Rio Arriba</b>

Latitude 36.7522392 Longitude -107.47149

**NATURE OF RELEASE**

Type of Release <b>Natural Gas</b>	Volume of Release <b>1.954 MMcf</b>	Volume Recovered <b>0</b>
Source of Release <b>Vent Valve (B Valve)</b>	Date and Hour of Occurrence <b>Unk.</b>	Date and Hour of Discovery <b>April 10, 2014 @ 4:00 p.m.</b>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom? <b>Lisa Hunter</b>	Date and Hour <b>April 24, 2014 @ 8:00 a.m.</b>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*  
N/A



Describe Cause of Problem and Remedial Action Taken.\*

**Equipment malfunction caused the Vent Valve (or B Valve) to remain hung open for approximately 72 hours releasing approximately 1.954 MMcf of Natural Gas into the atmosphere. Release was stopped and malfunction corrected by MSO.**

Describe Area Affected and Cleanup Action Taken.\*

**No liquid involved in the release. No remediation required.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <b>Lisa Hunter</b>	Approved by Environmental Specialist: 	
Title: <b>Field Environmental Specialist</b>	Approval Date: <b>5/1/14</b>	Expiration Date:
E-mail Address: <b>Lisa.Hunter@cop.com</b>	Conditions of Approval:	Attached <input type="checkbox"/>
Date: <b>April 28, 2014</b>	Phone: <b>(505) 326-9786</b>	

\* Attach Additional Sheets If Necessary

#NLS 141 215 3478