



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

5 HWT 1M
7:30 AM - JUN-2014

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 10-JUNE-2014 Operator COMACO API # 30-045-33899
Property Name SAN JUAN 32-7 Well No. 36 F Location: Unit E Section 8 Township 32 Range 7
Well Status (Shut-In or Producing) Initial PSI: Tubing 221 Intermediate 78 Casing 221 Bradenhead 4

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min		78	225		228
10 min		78	226		229
15 min		78	227		229
20 min					230
25 min					230
30 min					231

FLOW CHARACTERISTICS		BRADENHEAD	INTERMEDIATE
Steady Flow			X
Surges			
Down to Nothing	✓		
Nothing			
Gas	✓		X
Gas & Water			
Water			

RCVD JUN 10 '14

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

OIL CONS. DIV.

DIST. 3

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE .5

REMARKS:

OPENED THE BRADENHEAD AND ~~IT~~ IT BLEW DOWN TO
NOTHING IN 1 SECOND. OPENED THE INTERMEDIATE AND IT ~~BLEW~~ ^{HAD A 416 PSI} ~~FOR~~ BLOW FOR
THE ENTIRE TEST. REQUESTED A GAS ANALYSIS AND GAS STREAM.

By [Signature]

Witness [Signature]

(Position)

E-mail address _____