



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/District/III/3district.htm>

JUL 14 2014
OIL CONS. DIV. DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 14 JUL 2014 Operator BALWORTH API #30-0 39-18201

Property Name SAN JUAN 30-6 Well No. 41 Location: Unit Section 13 Township 30 Range 6

Well Status (Shut-In or Producing) Initial PSI: Tubing 111 Intermediate 87 Casing 111 Bradenhead 87

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			FLOW CHARACTERISTICS	
	Bradenhead	INTERM		BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg
TIME					
5 min		15	112		111
10 min		15	112		111
15 min		15	112		112
20 min		16	112		111
25 min		16	112		111
30 min		19	111		111
Steady Flow <u>X</u> <u>X</u>					
Surges <u> </u>					
Down to Nothing <u> </u>					
Nothing <u> </u>					
Gas <u>X</u> <u>X</u>					
Gas & Water <u> </u>					
Water <u> </u>					

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 12

INTERMEDIATE 20

REMARKS:

OPENED THE BRADENHEAD AND IT PRODUCED FOR THE ENTIRE TEST. THE INTERMEDIATE PRESSURE FELL DURING THE BRADENHEAD TEST SHOWING COMMUNICATION, DROPPING TO 18 PSI BY THE END OF THE TEST. OPENED THE INTERMEDIATE AND IT PRODUCED FOR THE ENTIRE TEST.

By [Signature]

Witness [Signature]

Prod. Specialist
(Position)

E-mail address