



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7/8/14 Operator XTO API #30-0 45-32592

Property Name Stanolind Gas Com Well No. 4 Location: Unit K Section 9 Township 32 Range 12

Well Status(Shut-In or Producing) Initial PSI: Tubing 31 Intermediate 100 Casing 31 Bradenhead 11

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead		INTERM	
TIME		Int	Csg	Int	Csg
5 min	0	100	32	0	34
10 min	0	100	32	0	34
15 min	0	100	33	0	35
20 min				0	35
25 min				0	35
30 min				0	35

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	✓	✓ down to vapor
Nothing		
Gas		OIL CONS. DIV-DIST. 3
Gas & Water		JUL 08 2014
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

Bradenhead down to nothing in 23 seconds
Intermediate blew down to slight blow in 49 seconds, down to vapor
only in 14 mins. Requested gas analysis.

By Ken Durham
Pool Foreman
(Position)

Witness Paul Wicks

E-mail address: ken-durham@xtoenergy.com