



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

RCVD JUL 31 '14

OIL CONS. DIV.

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

DIST. 3

Date of Test 31-JULY-2014 Operator BURLINGTON/COMAL API #30-0 45-32885

Property Name STATE COMAL Well No. 367 Location: Unit Section 32 Township 31 Range 8

Well Status(Shut-In or Producing) Initial PSI: Tubing 108 Intermediate 0 Casing 109 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM		
	BH	Bradenhead	Csg	Int	Csg	
TIME						
5 min	/	0	109	/	109	
10 min	/	0	109	/	109	
15 min	/	0	109	/	109	
20 min						
25 min						
30 min						

FLOW CHARACTERISTICS		BRADENHEAD	INTERMEDIATE
Steady Flow			
Surges			
Down to Nothing			
Nothing	X		X
Gas			
Gas & Water			
Water			

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0 INTERMEDIATE 0

REMARKS: OPENED THE BRADENHEAD AND NOTHING CAME OUT
OPENED THE INTERMEDIATE AND NOTHING CAME OUT.

By Brad Parkes
MSE
(Position)

Witness John DePue

E-mail address