



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-6-14 Operator Wagon Road API #30-0 45-05642
Property Name West Bisc. 44 Well No. 144 Location: Unit 34 Township 26 Range 13
Well Status (Shut-In or Producing) Initial PSI: Tubing 0 Intermediate 1/A Casing 0 Bradenhead 21

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead				
	BH	Int	Csg	Int	Csg
TIME					
5 min	0		0		
10 min	0		0		
15 min	0		0		
20 min	0		0		
25 min	0		0		
30 min	0		0		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	<u>1 Vapor</u>
Surges	
Down to Nothing	
Nothing	
Gas	<u>1</u>
Gas & Water	
Water	

DIST. 3
OIL CONS. DIV.
RCVD AUG 6 '14

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 1 INTERMEDIATE 1/A

REMARKS:

Medium blow to vapors at 14 seconds.
Vapors 5 min - 10 min - 15 - 20 - 25 - 30
After 5 min medium light blow 44 seconds then light through
1/4" hole
By Jacob H. H. H. Witness Monica C. H. H.
(Position)
Re-test in 1 year
2H

E-mail address _____