



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6176 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8/13/2014 Operator COPC API #30-0 39-20361

Property Name San Juan 27-5 Well No. 124 Location: Unit H Section 28 Township 22 Range 5

Well Status (~~Shut-In~~ or Producing) Initial PSI: Tubing 207 Intermediate 23 Casing 207 Bradenhead 2

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead				
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	23	210	0	214
10 min	0	23	211	0	215
15 min	0	23	212	0	216
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	☒
Surges	☐
Down to Nothing	☒
Nothing	☐
Gas	☐
Gas & Water	☐
Water	☐

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☐ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

OIL CONS. DIV DIST. 3

AUG 13 2014

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

Down to fumes in 3 sec. on braden head, nothing in 7 min.
Intermediate down to slight blow in 5 min. down to fumes at 9 min.

By Raymond Baldonado

Witness Paul Wicks

MSO
(Position)

E-mail address Raymond.Baldonado@conocoPhillips.com