



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/district.htm](http://emnr.state.nm.us/ocd/District%20III/district.htm)

RCVD AUG 19 '14

OIL CONS. DIV.

DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8/19/2014 Operator COPC API #30-0 39-06876

Property Name San Juan 27-5 Well No. 17 Location: Unit M Section 29 Township 27 Range 5

Well Status(Shut-In or Producing) Initial PSI: Tubing 182 Intermediate 2 Casing 182 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead				
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	3	182	0	183
10 min	0	3	183	0	184
15 min	0	3	183	0	184
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	✓
Nothing	✓
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

Nothing on bradenhead. Intermediate blew down to nothing
in 35 seconds. Brian took gas samples on bradenhead, intermediate,
and the casing.

By B-A-B
MSO/COPC
(Position)

Witness Paul Wiche

E-mail address _____