



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-18-14 Operator Energex Cos API #30-0 39-26575
Property Name Jicarilla 152W Well No. 2M Location: Unit J Section 5 Township 26 Range 5
Well Status (Shut-In or Producing) Producing Initial PSI: Tubing 62 Intermediate 11A Casing 65 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM		
	BH	Int	Csg	Int	Csg	
TIME						
5 min	<u>0</u>		<u>66</u>			
10 min	<u>0</u>		<u>66</u>			
15 min	<u>0</u>		<u>67</u>			
20 min						
25 min						
30 min						

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	<u>✓</u>
Nothing	
Gas	<u>DIST 3</u> <u>oil sands flow</u>
Gas & Water	
Water	<u>RCVD AUG 18 '14</u>

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 11A

REMARKS:

puff when opened. Extra 2 pool-

Cleared

By MICHAEL L DEAN

Witness

Monica Kuehling

PRODUCTION FOREMAN
(Position)

E-mail address _____