



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3distric.htm](http://emnr.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7/30/14 Operator WPX Energy API #30-0 43-21204

Property Name Chaco 2306-19E Well No. 205H Location: Unit E Section 19 Township 23N Range 06W

Well Status (Shut-In or Producing) Initial PSI: Tubing N/A Intermediate N/A Casing Ø Bradenhead Ø

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead			Int	Csg
	BH	Int	Csg		
TIME					
5 min	Ø	-	Ø		
10 min	Ø	-	Ø		
15 min	Ø	-	Ø		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	X
Gas	
Gas & Water	
Water	

RCVD AUG 18 '14
OIL CONS. DIV.
DIST. 3

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD Ø INTERMEDIATE _____

REMARKS:

No pressure on BH. Test performed with well in a logged off state prior to well stimulation. No tubing in well at time of test. BH valve left open to atmosphere after test.

By Cody Boyd
Field Technician
(Position)

Witness _____

E-mail address Cody.boyd@wpxenergy.com